

---

**From:** John A Cima (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=JOHN171D28]  
**Sent:** 1/26/2016 9:05:29 AM  
**To:** Michael J Winters (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=MIC1082]; Michael A Glagola (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Mic0210]; Doug Wight (Generation - 34) [/O=DOMINION/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=Dougla7]  
**Subject:** RE: Possum Toe Drain Separation Drawing

Agreed - Looks like a good concept but more details needed. I would also caution that based on the outlet condition of the 72 discharge pipe from this box (2/3 full of sediment), the box will have to be cleaned out of accumulated sediment (vacuum truck?) in order to bolt the HDPE pipe to the floor of the box.

John C.

**From:** Michael J Winters (Generation - 34)  
**Sent:** Tuesday, January 26, 2016 8:50 AM  
**To:** Michael A Glagola (Generation - 34); Doug Wight (Generation - 34); John A Cima (Generation - 34)  
**Subject:** RE: Possum Toe Drain Separation Drawing

This is probably fine for DEQ, but needs more detail to be constructed. Maybe already in the works, but GAI needs to provide support details, seal details, anchor details etc.

Mike W

**From:** Michael A Glagola (Generation - 34)  
**Sent:** Monday, January 25, 2016 2:50 PM  
**To:** Doug Wight (Generation - 34); John A Cima (Generation - 34); Michael J Winters (Generation - 34)  
**Subject:** FW: Possum Toe Drain Separation Drawing

FYI

**From:** John Klamut [<mailto:J.Klamut@gaiconsultants.com>]  
**Sent:** Monday, January 25, 2016 1:54 PM  
**To:** John Glover; [rwilliams@gloverconstruction.com](mailto:rwilliams@gloverconstruction.com)  
**Cc:** Scott Quinlan; Brian Bullock; Michael A Glagola (Generation - 34); John DeBarbieri  
**Subject:** Possum Toe Drain Separation Drawing

John/Reuben,

This is our working drawing for the toe drain separation. We will be sending this to DEQ, please review and provide any edits or comments, we want to be sure what we send them is correct.

Give me a call with any questions.

Thanks,

John

**John R. Klamut, P.E.**  
Engineering Manager

**GAI Consultants, Inc.**

4200 Triangle Lane, Export, PA 15632-1358

412.399.5425 | C 724.421.6740 |     



transforming ideas into reality<sup>®</sup> since 1958 | [gaiconsultants.com](http://gaiconsultants.com)

CONFIDENTIALITY NOTICE: This communication contains confidential information belonging to the sender and may be legally privileged. This communication is solely for the use of its intended recipient. If you are not the intended recipient, inform the sender of the error and remove this email from your system. If this transmission includes any technical information, design data, and/or recommendations, they are provided only as a matter of convenience and may not be used for final design and/or construction.

00013045